

NUMBER OF COPIES RECEIVED		6	
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		
PRODUCTION OFFICE			
OPERATOR			

# NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103

## MISCELLANEOUS REPORTS ON WELLS

RECEIVED

(Submit to appropriate District Office as per Commission Rule No. 2, 1961)

Name of Company <b>Tom Boyd &amp; Jack Plemons</b>		Address <b>102 Second Second, Artesia, New Mexico</b>			
Lease <b>Continental State "27"</b>	Well No. <b>5</b>	Unit Letter <b>D</b>	Section <b>27</b>	Township <b>17</b>	Range <b>29</b>
Date Work Performed <b>2-4-61</b>	Pool <b>Grayburg-Jackson</b>		County <b>Eddy</b>		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):  
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

On 2-4-61 we run 272 feet of used 24# 8 5/8" casing and cemented with 50 sacks of cement.

On 2-6-61 drilled cement plug & tested one hour. Hole dry.

Witnessed by <b>Tom Boyd</b>		Position <b>Co-owner</b>		Company <b>Tom Boyd &amp; Jack Plemons</b>		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P P T D	Producing Interval		Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by <i>M. L. Armstrong</i>				Name <i>Tom Boyd</i>		
Title <i>SIL AND OIL INSPECTOR</i>				Position <b>Co-owner</b>		
Date <b>MAR 24 1961</b>				Company <b>Tom Boyd &amp; Jack Plemons</b>		