## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 Copies to Appropriate

(This space for State Use)

APPROVED BY For Record Cnly
CONDITIONS OF APPROVAL, IF ANY:

District Office						
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	Box 1980, Hobbs NM 88241-1980 2040 Pacheco St.			WELL API NO. 30-015-03190		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM	87505	5. Indicate Type		FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Ga E-4201			
SUNDRY NOT	CES AND REPORTS ON WEL	LS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Empire Abo Unit "C"			
1. Type of Well: OIL GAS WELL X WELL	OTHER				,	
2. Name of Operator ARCO Permian			8. Well No. 45		,	
3. Address of Operator P.O. Box 1089 Eunice, NM 8	38231		9. Pool name or Empire Abo	Wildcat		
4. Well Location		24	10	u		
Unit Letter L 1980	Feet From The	Line and 33	Peet Fro	m TheW	Line	
Section 30	Township 195 R	inge 29E	NMPM	Eddy	County	
Section 30	Township 193 Re	er DF, RKB, RT, GR, etc				
		3664° CR				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
					Г	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X	ALTERING CASI	NG _	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ABAN	IDONMENT _	
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB		ſ	
OTHER:		OTHER:				
12. Describe Proposed or Completed Opwork) SEE RULE 1103.	rations (Clearly state all pertinent det	tails, and give pertinent da	tes, including estin	nated date of startin	ig any proposed	
TD: 6350' PBD: 6128'	CIBP: 6178° PERFS: 6288	-6298*	22.2.3.3.	25.26(2) <sub>22,23</sub>		
07/23/98: MIRUPU ND WH NU BOP.						
07/24/98: RIH w/bit, scraper, and tbg to PB @ 6128'.						
07/27/98: RIH w/pkr & tbg. Tag up on CIBP. Test to 800#, held good.						
07/28/98: Dig out around wellhead. 4-1/2" csg eaten up 4° below sufaçe. Rám Con de						
Casing Integrity Log. RIH w/10 jts & RBP. Set RBP @ 700'.						
07/29/98: RIH w/34 jts. Set RBP @ 1360'.						
08/03/98: Dig out around wellhead to good csg.						
08/04/98: Cut 4-1/2" csg 3' from surf. Weld in new section 4-1/2" and wellhead flange. Awaiting Engineering Evaluation for repair or P&A>						
I Idings. And It my Engineer my Evaluation for Tepan of Tero						
I hereby certify that the information above is	true and complete to the best of my knowled;	ge and belief.				
SIGNATURE MULLI HI	140	TLE Administrative	Assistant	DATE	06/28/99	
TYPE OR PRINT NAME Kelle D. Mu	rrish			TELEPHONE NO. 5	<u>05-394-1649</u>	