NGINEER

(SUBMIT IN TRIPLICATE)

## UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

Land Off	. Las Cruses
Lease No.	G28480(A)
	Firem A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO CHANGE PLANS	-		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	1
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	1
		SUPPLEMENTARY WELL HISTORY	1
	1 1		
	<u></u>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	Lego Hil	le, lies hariso December 6, 19.61
Well No5 is located	<b>2316</b> ft. from ${N \brace S}$ line ar	and 2016 ft. from $\left\{ \begin{array}{c} E \\ W \end{array} \right\}$ line of sec 30
State Section 30 (3/ Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)
indesi greted (Field)	(County or Subdivision)	(State or Territory)
The elevation of the	above sea level is3653	1_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 11-22-61 we ran 788° of 8 5/8" OD Srd thrd 20# HS ST&C used casing to 800° and casented with 150 sax 50-50 posmix W/6# gel and 100 sax 50-50 posmix W/X# CaClg. After standing casested for 24 hours we pressured upon casing to 1000 lbs. Tested OK. He then drilled plug and blow hele dry with gas. Water shut off proved complete and drilling was resumed.

RECEIVED

DEC 7 1961

U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company General American Oil Company of 1				
Address	ph/ (			
loce Hills, New Hexico	By Race &			
	Title District Separintendent			