

APPROVED

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 028480(a)

Unit Green A

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

DEC 8 1961
RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

DEC 12 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Leeco Hills, New Mexico December 6, 1961

Well No. 5 is located 2310 ft. from N line and 2310 ft. from E line of sec. 30
SW 1/4 Section 30 17-S 29-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Edgy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3653 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 12-3-61 we ran 6302' of 5 1/2" OD 8rd thrd 15.5# JS ST&C new Spang casing to 6313' and cemented with 150 sac 50-50 pozzix W/18% gel and 3% salt and 416 sac 50-50 pozzix and liner W/2% gel.

Casing and cement were tested during subsequent acid treatment to 2900 psig and both proved OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company General American Oil Company of Texas

Address P. O. Box 416

Leeco Hills, New Mexico

By R. J. Heard
R. J. Heard

Title District Superintendent