

Form 3160-5  
(June 1990)

RECEIVED  
AUG 25 10 53 AM '93

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.  
LC 028775B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. RJU TR 1A

# 2

9. API Well No.

10. Field and Pool, or Exploratory Area  
GRAYBURG JACKSON

11. County or Parish, State  
EDDY

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MERIDIAN OIL INC.

3. Address and Telephone No.

P.O. Box 51810 Midland, TX 79710

915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NE/NE, SEC 34 T17S, R29E

440 FNL & 440 FEL

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/1/93: MIRU. RIH W/TBG OPEN ENDED TO 2500'. CIRCULATED HOLE W/10 PPG GELLED BRINE. PMPED 35 SXS BALANCE PLUG. WOC. RIH W/TBG TO TAG PLUG. PLUG WAS NOT THERE. PMPED 35 SXS CMT @ 2500. WOC

8/2/93: RIH W/CICR ON TBG TO 3030'. SET RETAINER. STUNG OUT. CIRCULATED HOLE W/10 PPG BRINE MUD. SQZD 50 SXS CMT BELOW. CAPPED W/6 SXS CMT. RIH W/CIBP SET @ 2460'.

8/3/93: DRLD FOR 4 HRS MADE NO HOLE. CONTACTED SHANNON SHAW W/BLM AND WAS GIVEN OK TO CHANGE PROCEDURES FROM SETTING CICR @ 2400 TO SETTING IT @ 2046. RIH W/CICR TO 2046. PMPED 50 SXS CMT. ON TOP CICR.

8/4/93: CUT 8 5/8" CSG OFF AT 955;. RIH W/TBG TO 1010. PMPED 10 SXS CMT. WOC

8/5/93: RIH. TAG STUB PLUG, WASN'T THERE. PMPED 30 SXS CMT. WOC. ATTEMPTED TO TAG STUB PLUG, WAS NOT THERE. PMPED 15 SXS LCM. PMPED 30 SXS CMT. WOC. PMPED 10 SXS LCM. PMPED 30 SXS CMT. WOC.

8/8/93: RIH. TAGGED CSG STUB AT 955. MIXED 100 SXS GELLED MUD, 60 SXS LCM, PMPED @ 955. WOC. PMPED 100 SXS GELLED MUD AND 30 SXS CMT. WOC.

Approved by (signature) of the well bore  
utility under bond is retained until  
surface restoration is completed.

Post ID-2  
9-12-93  
PLA

14. I hereby certify that the foregoing is true and correct

Signed

DONNA WILLIAMS

Title PRODUCTION ASSISTANT

Date 8/24/93

(This space for Federal or State office use)

(OPIC SCD) JOE G. LARA

Approved by

Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

9/22/93

RJU TR 1A # 2  
PLUG AND ABANDON CONT.

8/9/93: RIH TAGGED CSG STUB @ 955'. NO CMT ON TOP. PMPED 30 SXS CMT. WOC.  
CONTACTED BLM AND WAS GIVEN THE OK TO DUMP PEA GRAVEL. DMPED 4 YDS PEA  
GRAVEL DOWN CSG. RIH TAGGED TOP OF GRAVEL @ 870. PMPED 30 SXS CMT ON TOP.  
WOC. RIH TAGGED CMT @ 896. RIH W/TBG OPEN ENDED TO 896. PMPED 30 SXS CMT.  
8/10/93: RIH TAGGED PLUG @ 862. RIH W/TBG. PMPED 20 SXS CMT AT 850. WOC. RIH  
TAGGE DPLUG @ 827. FILLED HOLE W/FRESH WATER. RU WIRELINE. RIH TO 760.  
PERFORATED 8 HOLES. POOH W/WIRELINE. WELDED ON HEAD. NU BOP. TRIED TO  
ESTABLISH CIRCULATION. WELL WOULD NOT. PMPED 50 SXS CMT AT 750. WOC  
8/11/93: RIH TAGGED PLUG AT 636. TRIED TO LOAD HOLE. HOLE WOULD NOT LEAD RU  
WIRELINE. PERFORATED AT 360. TRIED TO ESTABLISH CIRCULATION, WOULD NOT.  
PMPED 130 SXS CMT. WOC. RIH TAGGED PLUG AT 130. LOADED HOLE. RIH W/WIRELINE  
PERFORATED AT 130. PMPED 100 SXS CMT. WOULD NOT CIRCULATE. WOC.  
8/12/93: RIH TAGGED PLUG AT 117. COULD NOT LOAD HOLE. PMPED 30 SXS CMT WOC. RIH  
TAGGED PLUG AT 117. PMPED 30 SXS CMT. WOC.  
8/15/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT.  
8/16/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT  
8/17/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT  
8/18/93: RIH TAGGED PLUG AT 117. MIXED CACL2 W/CMT PMPED 20 SXS. WOC. MIXED  
CACL2 W/CMT. PMPED 30 SXS WOC. STARTED PMPING CMT. SHOWED SIGNS OF CIRC.  
PMPED 120 SXS CMT.  
8/19/93: RIH TAGGED PLUG AT 117. GIVEN OK BY BLM TO DUMP 20' PEA GRAVEL DOWN  
10" AND FILL W/CMT TO SURFACE. PMPED 55 SXS CMT FILLED 10" CUT OFF CSG 3' BELOW  
SURFACE. INSTALLED P & A MARKER.

LOCATION HAS NOT BEEN CLEANED AS OF THIS DATE. WILL FILE FOLLOWUP SUNDRY  
UPON COMPLETION OF CLEAN UP.

RECEIVED

AUG 25 10 53 AM '93

CARROLL  
AREA