Submit 3 Copies to Appropriate District Office


State of New Mexico Energy, winerals and Natural Resources Department

Form C-101	
Revised 1-1-85	į

DISTRICT I P.O. Box 1980	Hobbe NM	88240
I.O. BOX 1384	, 11000t, 14m	00270

WELL API NO.	U.
30-015-04058	
5. Indicate Type of Lease STATE X	FEE []
6. State Oil & Gan Leane No.	
B-2130	

. Box 1980, 110004, 1111 00210		30-015-04058					
DISTRICCIII P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8	17504-2088	5. Indicate Type of Leane STATE X FEE				
DISTRICTIII 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gan Leane No. B-2130				
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIF (FORM C-101)	7. Lesse Name or Unit Agreement Name						
i. Type of Well: OL GAS WELL WELL	one Water]	Injection Well	Burnham, Grayburg, San Andres Unit, Tract #1				
2. Name of Operator			8. Well No. 3				
Anadarko Petroleum Co	orporation 000	0817	9. Pool name or Wildcat 001277				
PO Box 130, Artesia,	NM 88211-0130		Square Lake-GB-SA				
4. Well Location Unit Letter H : 1980	Feet From The North	Line and660	Feet From The East Line				
Well Location Unit Letter H 1980 Feet From The North Line and 660 Feet From The East Line							
	propriate Box to Indicate	Nature of Motice, Ro	eport, or Other Data				
NOTICE OF INTER	ITION TO:	SUB	SEQUENT REPORT OF				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING LI				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	r-1				
PULL OR ALTER CASING		CASING TEST AND CE					
OTHER:		011121112	JIUI II				
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEERURE 1103. Note: This well failed the NMOCD Mechanical Integrity Test ran in Note: This well failed the NMOCD Mechanical Integrity Test ran in Harch. We have now Thed the well as outlined below. We are asking for a 6 month period of temporary abandonment, til a decision can be made whether to F&A or repair casing and reactivate the well. The NMOCD was notified to witness before the work began. 1. RUFU. TOH with tbg and packer. 2. WIH with a CIBP and set at 2810' to isolate the Grayburg period. 3. Circulated hole with fresh water and chemical. TOH. 4. WIH with a packer and tested casing for leaks. Found holes in 12 1995 casing from 500' to 929' and a 150' per 5 minutes leak between 12 1995 929' and 1297'. TOH. 5. WIH with tension packer on 2 3/8" internally plastic coated tbg CON. DIV. 5. WIH with tension packer on 2 3/8" internally plastic coated tbg CON. DIV. 5. WIH with casing below the packer for 30 minutes. OK. Chart and well bore diagram are attached. 6. RDFU. Left the packer set in this well to keep the casing integrity. All bradenhead valves were left open and will be monitored to check for water flows. 1 hereby cordly that the information above is true and complete to the best of my knowledge and belief. 1 hereby cordly that the information above is true and complete to the best of my knowledge and belief.							
Signature Mike Braswe			(505) 677-2411 1818/1008 NO.				
(This space for State Use) ORIGINAL SIGNED DISTRICT II SUPE	BY TIM W. GUM RVISOR	III.P.	JUN 1 5 1995				
MINUTED TI							





PROJE T COMPUTATIONS

NO. _____ OF ____ SHEETS

DATE	PROJECT	јов но. <u>6-6-95</u>
BY	снк.:	SUBJECT Burnham # 1-3 WII
Casing leaks 1. Soo' to 1297' Packer on 23'8' Aby at 1297"		Calculated CT @ 315' 85/1"@571' W/25 sx Top of Salt @ 575' Calculated cement top @ 837' XE Base of salt @ 1300'
CIBP @ 2810		400 (2388 cine 7" @ 2450 "/1005x (Grayborg top @ 2754) (Perfs from 2410 - 3176 (Perfs from 2410 - 3176 (12" casing stub@ = 3032 - (3212 013187) (12" casing stub@ = 3032 - (3212 013187) (12" line, @ 3196' cine Tunk @ 3200' (1/6/73)