

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 029020J

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

MURPHY MINERALS CORPORATION

3. ADDRESS OF OPERATOR

P. O. Box 2164, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State laws.
See also space 17 below.)
At surface

660 FNL, 660 FEL Sec. 3

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3753 G.L.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Parke

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Sq. Lake, Gbr. S.A.

11. SEC. T., R., N., OR BLK. AND
SURVEY OR AREA

Sec. 3

T17S, R30E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

12-19-75 Treated well with 1,000 gal. 15% HCl, 41,000# 20-40 sand,
9,000# 10-20 sand, 70,000 gal. gelled water. 450# Gypban.
200# J-116 (Diverter) and 300# J-665 (Diverter in 3 stages)
Max. T.P. 5100, Average T.P. 4800 psi. ISIP 2400 psi.,
15" SIP 2200, @14 BPM.

12-20-75 Reversed out sand. Ran tubing and rods. Put well on pump.

RECEIVED
JUN 23 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

T. M. Boye

TITLE

Agent

DATE

6/22/76

(This space for Federal or State office use)

APPROVED BY

COMMISSIONER OF APPROVAL, IF ANY:

TITLE

DATE