

Las Cruces

(SUBMIT IN TRIPLICATE)

Land Office


029020(J)

Lease No.

R. D. Collier

Unit

Make sure



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Parks "J" September 10, 19 57

Well No. 3 is located 1980 ft. from [N] line and 1980 ft. from [E] line of sec. 3

CSW 1/2 Sec. 3 17 S. 30 E. N.M.P.M.

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Square Lake Eddy New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10 sack plug on bottom. Knocked pipe off at 2000' and set 10 sack plug on stub. Set plug at 400 feet in 8 inch pipe. Knocked 8 inch off at 200 feet and mudded to surface. Set 15 sack plug and marker.

RECEIVED  
NOV 8 1963  
D. C. C.  
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. D. Collier

Address Artesia, New Mexico

Box 798

By

*[Signature]*

Title