Form 3160-5	UNIT STATES	SURMIT IN TRIDITS TO	Form approved. Budget Bureau No. 1004-0135
November 19	83) DEDARTATAL E TUE INTE	ERIGR Jeers Hee)	5. LEASE DESIGNATION AND SEELAL NO.
	BUREAU OF LAND MANAGEM		LC-02 <b>9020-</b> J
(Do no	SUNDRY NOTICES AND REPORTS to use this form for proposals to drill or to deepen or pl Use "APPLICATION FOR PERMIT—" for su	S ON WELLS  lug back to a different reservoir.  ch proposals.)	6. IF INDIAN, ALEOTTEE OR TRISE NAME
OIL X	GAS THER	RECEIVED BY	7. UNIT AGREEMENT HAME
2. NAME OF O	PERATOR	MAY -1 1987	8. FARM OR LEASE NAME Parke Federal
MURPHY	OPERATING CORPORATION V	11387	9. WELL NO.
••		2-2648 O. C. D.	4
See Also an	ox 2648, Roswell, New Mexico 8820 well (Report location clearly and in accordance with size 17 below.)	any Stafe reoutfementer	10. FIELD AND FOOL, OR WILDCAT
At surface			Square Lake Grayburg San Andres
Unit Lt	r. H, 1980' FNL & 660' FEL, Sec. 3	, T-17S, R-30E	Sec. 3, T-17S, R-30E
14. PERMIT NO	. 16. ELEVATIONS (Show wheth	er DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3750' G. L.	<u> </u>	Eddy New Mexico
16.	Check Appropriate Box To Indica	ie Nature of Notice, Report, or	Other Data
	NOTICE OF INTENTION TO:	BUDAL	EQUBIT REPORT OF:
	TREAT MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CABING
PRACTURE BHOOT OR		SHOOTING OR ACIDIZING	X ABANDONMENT®
REPAIR W	CHANGE PLANS	(Other)	its of multiple completion on Well
(Other)		Completion or Recon	upletion Report and Log form.)
proposed	ROPOSED OR COMPLETED OPERATIONS (Clearly state all per work. If well is directionally drilled, give subsurface this work.) •	locations and measured and true vert	co. including for all markers and zones perti-
4-6-87	RU PU & TIH. TOH w/rods & pump. elev. & TOH & layed dn. 2-3/8" the		& mud jt. Changed .
4-7-87	Picked up notch out 2-3/8" collar @ 2961.59'. Btm. perf @ 2902' - of rat hole. TOH to pick up pkr.	2908' 3 JSPF - 18 holes	
4-8-87	Picked up Pkr. & TIH to 2772' abo	ove 4" liner & set pkr.	Pumped chemical as
·	follows:	ACC	CEPTED FOR RECORD
	500 gals. cor 12 bbls. flu		APR 2 7 1987
	SD. Wait on chemical 24 hrs.	CAR	ILSBAD, NEW MEXICO
4-9-87	23 hrs. SITP. Tbg. on vacuum. Follows:	RU acid trk. & completed	d acid job as
		•	CONTINUED ON PAGE 2
18. 4 hereby c	ertify that the foregoing is true and correct		
SIGNED _	Lois N. Brown TITLE	Production Clerk	DATE April 20, 1987
This space	ec for Federal or State office DBC)		
	ONS OF APPROVAL, IF ANY:		DATE

## MURPHY OPERATING CORPORATION



UNITED BANK PLAZA, SUITE 300
400 NORTH PENNSYLVANIA AVENUE
POST OFFICE BOX 2648
ROSWELL, NEW MEXICO 88202-2648

TELEPHONE 505 623-7210

SUNDRY NOTICES AND REPORTS ON WELLS April 20, 1987

Page 2

## PARKE FEDERAL WELL #4

Section 3, Township 17 South, Range 30 East, Eddy County, New Mexico Square Lake Grayburg San Andres Federal Lease No. LC-029020J

## 4-9-87 continued -

21 bbls. 15% NEFE acid
250 gals. 15% NEFE acid
250 # salt block mixed w/acid = good blk. action
357 gals. 15% NEFE acid
20 bbls. 2% KCL wtr. (flush)

Max. press. @ 3000# psi; Avg. press. @ 2750# psi.

Max. rate @ 3.8 BPM, Avg. rate @ 3.5 BPM

ISIP 2000# psi, 5 min @ 300# psi, 10 min. well on vacuum. Block action went from 700# psi = 3000# psi. Broke back. Rel. pkr. TOH & layed dn. same. Picked up tbg. anchor & TIH as follows:

Cut off piece of 2-3/8" tbg.	10.72'
Perf sub	3.00'
Seat Nipple	1.00'
Pump bbl.	14.32
4 jts. 2-3/8" tbg. J-55 4.70#	126.00'
tbg. anchor	6.00'
87 jts. 2-3/8" tbg. J-55 4.70#	2741.07'
Btm. of mud it.	2902.11'

Seat nipple set @ 2891.39'. Tbg. anchor set @ 2747.07'. Pulled 12,000# into anchor. Changed elev. Ran pump & rods as follows:

Pump 2 X 1-3/4" X 4" plunger 3/4" rod sub top of pump plunger 3/4" rods 16' X 1-1/4" polish rod w/8' X 1-1/2" liner