÷.	N	DIL CONS	COMMISSION
	-	an DD	
11NU	ED STATES	rtesia, NM	
	t of the interior		hudget Nureau No. 1001-0135 Expires: March 31, 1993
	AND MANAGEMENT		5. Lease Designation and Serial No.
			LC-029020-M
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. Il Indian, Allottee or Telbe Name
- Do not use this form for proposals to dri	ll or to deepen or reentry to a differe 1 PERMIT—'' for such proposals	nt reservoir.	N1 / 7
			N/A 1. If Unit of CA, Agreement Designation
SUBMIT IN TRIPLICATE			
			N/A R. Well Name and No.
Ull Well Well Water Injection Well			Federal Q #1
Name of Operation Anadarko Petroleum Corporation			9. AFI Well No.
7 Address and Telephone No.			30-015-04068
PO Box 130, Artesia, NM 8	8211-0130 (505)677-2	<u>₹⊥⊥</u>	Square Lake -GB-SA
4 Location of Well (Fouringe, Sec., T., R., M., or Survey De	activity		11. Connity or Facish, State
660' FNL & 660' FWL			Eddy, NM
Sec. 3, T175, R30E		HOF BEROM	
12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR			T, OH OTHEN DATA
TYPE OF SUBMISSION		E OF ACTION	·····
Notke at Intent		VED	Change of Plans
a 1	Recondering		New Construction
X Subsequent Report	- Li Mupping Mack Li Casing Repair JUL 1 4	1005	Water Shut-Off
D Final Abandonment Nutlcé	Altering Casing		Conversion in Injection
	X Mier Tamporari 1	Abandon	Dispuse Water Hinte: Report results of multiple completion on Well
		untral date of starting	Completion or Recompletion Report and Logform.) any proposed work. If well is directionally drilled,
13 Describe Proposed of Completed Operations (Clearly state a give subsurface locations and measured and true verifi-	al depths for all nurkers and zones pertinent to this wo	ik.≠	in maak nam in
Note: This well failed the NMOCD Mechanical Integrity Test ran in March. We have now TAed the well as outlined below. We are asking			
free a f month portiod of temporary abandonment, til a decision can			
to made whather to DLA or renair casing and reactivate the well.			
The NMOCD and BLM were notified to witness before the work began.			
<ol> <li>RUPU. TOH with tbg and packer.</li> <li>WIH with a CIBP and set at 2743' to isolate the Grayburg pay.</li> </ol>			
a gingulated hole with fresh water and Chemical, 10n.			
A with a packer and tested casing for leaks. Found notes in			
casing from 480' to 595' and a 50# per 10 minutes leak between 595' and 659'. TOH.			
r with tengion packer on 2 3/8" internally plastic coated tog			
and set packer at 659'. Ran casing integrity test by putting 500# on tbg and casing below the packer for 30 minutes. OK.			
500# on the and	casing below the packer pore diagram are attache	d.	indces. on
a popul toft the r	acker set in this Well	то кеер т	the casing
integrity, All b	oradenhead valves were I	eft open	and will be
monitored to the	eck for water flows.		
14. I hereby certify that the foregoing is true and correct	tile Field Foreman		Date 06-07-95
Signed _ Min Broswell			
(This space for CORIE. SED.)"JOE G. (	ARA PETROLEUM &	NGINEER	Date 7/11/95
A 44.	Tille		
	have casing repaired		
The IA II S C Section 1001, makes H & reline for any person	a knowingly and willfully to make to any department or	agency of the United	States any faise, fictilious or fraudulent statements
or representations as to any matter within its jurisdiction.	And Listenation on Reviet Cide		

\*See histinellen nit Navaran Birth



Mailing Address: P. O. Drawer 130 Artesia, New Mexico 88211-0130 Office Location: 132829 #1 Lovington Hwy. Loco Hills, New Mexico 88255 Off: (505) 677-2411 Fax: (505) 677-2414





