

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **LC 029020(M)**
Unit **C**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Attempt to Fish Tools ☒

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal "Q" ☒ **March 30,** 19 **64**
Well No. **2** is located **660** ft. from **N** line and **1980** ft. from **E** line of sec. **3**
NE 1/4 Sec. 3 **17S** **30E** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Square Lake **Eddy** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3744** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Attempted to clean out to 3167' T.D. Encountered string 5" tools at 2820'. Milled over tools to 2843'. Unable to recover from hole. Shut down operations, waiting on orders. Present well status T.A.

RECEIVED

MAY 6 1964

O. C. C. OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Ambassador Oil Corporation**

Address **Fort Worth, Texas**

Local - Box 260

Artesia, New Mexico 88210

By **E. W. Rickey**
Title **Supt.** **E. W. Rickey**

