

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office LAS CRUCES  
Lease No. 029020 H  
Unit 8

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <u>TEMPORARY</u>	<u>X</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

APRIL 10, 19 52

Well No. 3-H is located 1980 ft. from N line and 660 ft. from E line of sec. 3

SW 1/4 NW 1/4 Sec. 3 17 S 30 E N.L.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
SQUARE LAKE EDDY NEW MEXICO  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3726 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

to the extent that  
The production is exhausted ~~and~~ further producing is not justifiable.

A swedge is set on top of the 7" Casing with a valve, and is closed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A.S. WOOLLEY  
Address BOX 398  
LOCO HILLS  
NEW MEXICO  
By J. P. Briscoe  
Title SUPERINTENDENT

12/1/1911