


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office E
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	Returned to Active Status	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO ABANDON WELL	SUPPLEMENTARY WELL HISTORY	

Federal 'Q' (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

3

1980

660

3/19

SW 1/4 NW 1/4 Sec. 3 17-S 30-E NMPM
 Well No. is located Eddy ft. from [N] line and [E] ft. from [W] line of sec. 3
 West Square Lake New Mexico

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

(Field)

(County or Subdivision)

(State or Territory)

RECEIVED

APR 3 1964

O. C. C.
ARTESIA OFFICE

The elevation of the derrick floor above sea level is _____ ft.

This well was cleaned out to 1170' W.B. Nothing was encountered
 in the hole to obstruct pumping operations and the well was
 returned to active producing status under water flood develop-
 ment.

DETAILS OF WORK
 (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-
 ment.)

Ambassador Oil Corporation

Fort Worth, Texas

I understand that this work must have approval in writing by the Geological Survey before operations may be commenced.

Comptrol - Box 260

Address - Artesia, New Mexico 88210

Supt. E.W. Rickey
 By _____
 Title _____

RECEIVED
 APR 1 1964
 U. S. GEOLOGICAL SURVEY
 ARTESIA, NEW MEXICO