

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 020020 H
Unit F

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 6, 1951

Well No. 7

Well No. 7 is located 1295 ft. from N line and 1345 ft. from W line of sec. 3

36 36 Sec. 3

(1/4 Sec. and Sec. No.)

Square Lake

(Field)

175

(Twp.)

30E

(Range)

114N

(Meridian)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to drill this unorthodox location to the regular square lake pay. It is contemplated to set the oil string at about 2750'. The total depth will be about 3000'. Special permission was requested from New Mexico Oil Conservation Commission for the unorthodox location and was granted November 16, 1949, by Order No. 843, copy of which accompanies this notice.

Location staked by Vilas E. Cholden and plat is attached.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ROLAND OIL COMPANY

Address P. O. Box 456

Artesia, New Mexico

By J. L. Busine
Title Superintendent