

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYBudget Bureau No. 42-R358.4.
Form Approved.Land Office LC
Lease No. 060325
Unit F

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent report to return to production.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 21, 1964

Well No. 16 is located 660 ft. from S line and 660 ft. from E line of sec. 4
SE/4 SE/4 Sec. 4 17-S 30-E NM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11-16-63 Cleaned out with sand pump to 2947'. Ran 2937'
of 2" 80Z tubing and 2875' of 3/8" sucker rods.
Put well on production.

RECEIVED
FEB 27 1964
O. C. C.
ARTESIA OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Newmont Oil CompanyAddress Rowley BuildingArtesia, New MexicoORIGINAL SIGNED BY
H. J. LEDETTERBy _____
District Superintendent
Title _____