

N. M. O. C. C. COM
GEOLOGICAL SURVEY
WELL STATUS REPORT

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR

J. Cleo Thompson
4500 Republic Bank Tower, Dallas, Texas 75201

WELL NO. AND LEASE NAME

16 - Leonard "E"

LEASE NO.

LC 060325

COUNTY

Eddy

STATE

N. Mexico

Section 4 Township 17S Range 30E

Footage Location of Well:

460 feet from S line

460 feet from E line

Pool

Square Lake

1. When Was Well Shut-in or Last Produced?

February, 1972

RECEIVED

SEP - 3 1976

2. Type Well

☒ Oil Well

☐ Gas Well

☒ Temp. Abd. Well

☐

O. C. C.

ARTESIA, OFFICE

3. Producing Capability

BOPD Less than 1

MCFGPD _____

BWPD _____

Date Last Tested November, 1963

4. Is Well Considered Capable of Production in Paying Quantities?

☐ Yes

☒ No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

Not applicable

RECEIVED

SEP 02 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time.

To put in a future waterflood program.

7. What Are Future Plans For Operating Well (Include Estimated Dates)?

To continue on a temporary abandoned status until a waterflood unit is organized, hopefully in next two years.

I hereby certify that the foregoing is true and correct

SIGNED Jack Myers

TITLE Agent

DATE Aug. 30, 1976

(This space for Federal or State Use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

SEP - 2 1976

H. L. BEEKHUIS

ACTING DISTRICT ENGINEER