

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 000235

Unit I

RECEIVED

OCT 21 1969

O. C. C.
ARTEBIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|---|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... | |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... | X |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... | |
| NOTICE OF INTENTION TO ABANDON WELL..... | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 22, 19 67

Well No. 2 is located 1000 ft. from N line and 400 ft. from E line of sec. 7

Section 7
(14 Sec. and Sec. No.) 30E
(Twp.) (Range) (Meridian)
Adairson 30E New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth of hole 1000'. Lugged to bottom of casing, set 15 sack cement plug at 970', set cement plug at the base of the well at 970', set 15 sack cement plug at the base of the 10" pipe at 5'6", then put up customary dry hole marker. This work was done by C. E. Therman. He recovered 1000' of 7" pipe and 312' of 1 1/2" pipe.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVID SAMPSON

Address Millard Hughes

Antasia Hotel

Antasia, New Mexico

By _____

Title Authorized Agent