

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**  
Lease No. **061483**  
Unit **F**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 5, 1953

Well No. 6 is located 1650 ft. from N line and 2310 ft. from W line of sec. 7  
SE/4 NW/4 Sec. 7 17 S 30 E. NMPN  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Anderson Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 25 sx cement in shot hole and 10 sx cement at base of salt and 10 sx at top of salt. Salvaged 202 feet of 7" casing and 187 feet of 8-5/8" casing. Regulation marker placed at surface. Surrounding area cleared of refuse.

*Refer to Form C-110 in folder of  
Sheet #2 - 7-175-30E*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WILSON BROS. OIL COMPANY  
e/o C. O. Fulton  
Address P. O. Box 723  
Artesia, New Mexico

By C O Fulton  
Title Agent