

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORT ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☐ Oil Well ☐ Gas Well ☒ Other UNIT WATER INJECTION WELL

2. Name of Operator  
Burnett Oil Co., Inc.

3. Address and Telephone No.  
801 Cherry Street, Suite 1500, Fort Worth, TX 76102 817/332-5108

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Unit N, 660' FSL, 1980' FWL, Sec. 13, T17S, R30E

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.  
LC 030570A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation  
8910088670

8. Well Name and No.  
GJSAU #13

9. API Well No.  
30-015-04145

10. Field and Pool, or Exploratory Area  
Grayburg-Jackson

11. County or Parish, State  
Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Recompletion

☐ New Construction

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Subsequent Report

☒ Casing Repair

☐ Water Shut-Off

☐ Altering Casing

☐ Conversion to Injection

☐ Other

☐ Dispose Water

☐ Final Abandonment Notice

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This Unit water injection well failed the most recent NMOCD mechanical integrity test. We now propose to determine the source of the failure. Once found, we will do what is necessary for the well to pass the mechanical integrity test and to return this well to an active Unit water injection status. This may be a cement squeeze for a hole in the casing that is deep or replacement of the bad joint if the hole is near the surface.

RECEIVED

NOV 09 1995

OIL CON. DIV.  
DIST. 2

14. I hereby certify that the foregoing is true and correct

Signed

Title

Petroleum Engineer

Date

11/06/95

(This space for Federal or State office Use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any False, Fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side