



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 28773(a)  
Unit Block A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>2</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Los Hills, New Mexico Sept. 17, 1957

Well No. 14 is located 660 ft. from 1/4 line and 1900 ft. from E line of sec. 18

24 24 Sec. 18 17-5 20-5 N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Canyons-Judith Edy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3650 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On August 31, 1957 we ran 4 1/2" (100 joints) of 5 1/2" OD 14# and third 8-3 JS new CPM casing and cemented with 100 sack cement.

After allowing to stand cemented for 72 hours we drilled plug, bailed hole dry and re-ran bailer. As shut-off appeared complete drilling was resumed.

On Sept. 6, 1957 attempted to acidize with 435 gallons 20% HCl. Hole took all acid on bottom. Hooked up pump & circulated around casing.

On Sept. 7, 1957 we recomputed casing with 50 sack cement.

On Sept. 12, 1957 after standing cemented, drilling plug and testing we re-acidized with 1000 gals 20% HCl.

Casing withstood surface pressure of 2600 psi during treatment.

Cementing was done by Benton Oil Well Cementing Company.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL COMPANY OF TEXAS

Address P. O. BOX 416

LOS HILLS, NEW MEXICO

By R. J. Heard  
Title Field Superintendent