

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. NM 074936
Unit W. D. McIntyre "D"

SUNDRY NOTICES AND REPORTS ON WELL

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico, July 23, 19 62Well No. 10 is located 1650 ft. from S line and 1980 ft. from E line of sec. 21SE 1/4 21
(1/4 Sec. and Sec. No.)17S
(Twp.)30E
(Range)NM
(Meridian)Undesignated
(Field)Hddy
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9/26/60- ID 6995' - Dry Hole- Plugged & Abandoned as follows;

Fill hole with heavy mud and set;

25 Sk. Cement Plug 2/ 6870 to 6995'

25 " " " 1/ 4525 to 4650'

25 " " " 1/ 2940 to 3060'

25 " " " 1/ 2140 to 2260'

25 " " " 1/ 1580 to 1640'

Set 4" Regulation "Marker" in top of 8 5/8" OD Casing and bottom of cellar extending 4' above surface level- Filled cellar and pits, level location- well plugged & abandoned

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas CompanyAddress 520 E. Broadway, Hobbs, N.M.

By _____

Title Dist. Supt.