

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 060528Unit Maintenance

APPROVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Subsequent Report of Sandfill	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loco Hills, N. M. Feb. 23, 1955

Well No. 1-6 is located 330 ft. from N line and 2310 ft. from E line of sec. 21
NE 1/4, NE 1/4, Sec. 21 17-S 30-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Grayburg-Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3672 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)
RECORD OF PRODUCTION PRIOR TO WORKOVER: Pumped 2 MOPD. Total Prod. 71,516 BO.

RECORD OF RECOMPLETION: (1955)

- 1-21 Run Leco-Hills radioactivity survey from 2591 back to surface. Run caliper survey from 2590 to 2000.
1-24 Run 2567' of 2-1/2" EUE tubing with Gutherson 8-2 H-W packer at 2443 and H-1 hydraulic anchor at 2130. Loaded annulus.
1-25 Fractured as follows: 6 bbls. crude; 31 bbls. kerosene; 249 bbls. 24 gravity refined oil containing 15,400 lbs. sand. Flushed with 50 BO. Max. inj. press. 3700 psig; at end of flush 3200 psig. Total inj. time 34-1/2 min. Load oil 423 bbls. Pulled 2-1/2" EUE & packer.
1-26 Re-ran pumping installation.

RESULTS OF TREATMENT:

1-27 Pumped 50 bbls.

Understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL CO. OF TEXASAddress BOX 416LOCO HILLS, NEW MEXICO

By

R. J. HeardTitle Field Supt.