

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. & C. C. CO.

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Copy to SF
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0467930

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale H. Parke "A"

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22 - 17 - 30

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals.)

1. OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

SHEPANDOAH OIL CORPORATION ✓

3. ADDRESS OF OPERATOR

1500 Commerce Building - Fort Worth, Texas - 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit "L"

2100' FSL, 900' FWL Section 22 - T17S - R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,648' Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☒

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) Casing - oil string

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

T. D. 3,687'

7-21-76 Ran and set 96 joints of used 9.5# and 10.5# 4-1/2" J-55 pipe @ 3,685'.
Ran 500 gals. Halliburton mud blush ahead of 375 sks of Class "H" cement
w/5# salt and 10# sand and .3 of 1% CFR₂ - bumped plug @ 2400# - re-
leased and float shoe held OK.

After 7 hrs, ran temperature survey. Found TD @ 3,672' and top of ce-
ment @ 2,300' G.L.

RECEIVED

RECEIVED

AUG 16 1976

AUG 12 1976

D. C. C.
ARTESIA, OFFICE

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

C. W. Downey, Jr.

TITLE Operations Superintendent

DATE August 10, 1976

(This space for Federal or State Office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

AUG 12 1976

J. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side