

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 029020 H
Unit Woolley-McIntyre K

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8, 1951

Mc Intyre
Well No. 8-H is located 1775 ft. from N line and 1650 ft. from E line of sec. 23

SW 1 NE 1 SW 1 Sec 23 17 S 30 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Premier Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In checking our files we find that a water shut off with the 8 5/8" casing has not been filed on Mc Intyre 8-H.

We set 488' of 8 5/8" casing using 50 sacks of cement with heavy white mud top to bottom by Denton Oil Well Cementing Company on June 24, 1951.

Cement stood 72 hrs, and was bailed dry before drilling was resumed.

There was a small seep of water but not enough to drill with.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Roland Rich Woolley

Address Box 398

Loco Hills

New Mexico

By J. P. Brewer

Title Superintendent

