



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NOV 20 AM 9:41

Land Office **029020-B**
Lease No. **D.H. Parke**
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico **October 25, 1956**

Well No. **3** is located **1750** ft. from **N** line and **330** ft. from **E** line of sec. **23**
17S **30E** **10PM**
 (Twp.) (Range) (Meridian)
Premier **Eddy** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3661** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

FWO 3111 - Cleaned out to 3111, Fractured with 8000 gal oil & 8000# sand from 3084 to 3092. Max press 3800#, Min press 3200#. Injection rate 6.7 bbl per min. Fractured with 2000 gal oil & 2000# sand from 3039 to 3044. Max press 3800#, Min press 2600#. Injection rate 7.1 bbl per min. (Both fractures call 17-56)

Load oil recovered and on 10-24-56, well pumped 75 bbls new oil in 24 hours. Gas too small to measure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sinclair Oil & Gas Company**

Address **520 E. Broadway, Hobbs, N.M.**

By *[Signature]*

Title **District Superintendent**

Orig & Inc: USGS
cc: OGC

