

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION  
Drawer DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-030670 (6)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Grayburg Jackson Unit

8. Well Name and No.

TRACT 13 Well No. 35

9. API Well No.

30-015-04321

10. Field and Pool, or Exploratory Area

Grayburg Jackson

11. County or Parish, State

Eddy Co. New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

LAO ENERGY INC.

3. Address and Telephone No.

505 N. BIG SPRING, STE 105, MIDLAND TEXAS 79701 (910) 686-8600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FEET & 1980' FEET, SECTION 25, T-17-S, R-30-E  
Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

RECEIVED

JUL 21 1995

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

September - 1982:

DIST. 2

P&A Grayburg Jackson Unit 13-B by Severeing Casing Perforations (3 1/2")  
From 3300-3330' Down 3 1/2" Casing. Pore were Severeing And Casing was  
Left Fine or Cement. (3 1/2" Casing Had Been Circulation To Surface) Port ID-5  
Cut one shoulder, Reserve Location.

8-4-95  
P&A

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Mark R. Clark

Title

Engineer

Date

5/30/95

(This space for Federal or State office use)

Approved by

(ORIG. SCD.) JOE G. LARA

Title

PETROLEUM ENGINEER

Date

7/19/95