

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Las Cruces
Land Offic 1C 060528
Lease No.
Unit

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	----------------	-----	----------------	----	-------

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Return to Active Prod. Status X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		September 16,	19 64
Gra yburg-Jackson U Well No. 2-8 is located	1980 ft. from	line and $ft. \text{ from } \begin{cases} E \\ W \end{cases}$ line of sec	, 1/
TWY Of SW4 26	17-8	E MMFM (W)	
(1/ Sec. and Sec. No.)	(Twp.) Eddy (Range)	(Meridian) Hexico	
(Field)	(County or Subdiv		
The elevation of the derrick flo	or above sea level is	361 2 ft.	

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-Request was made on "Sommary 12, "Type to convert the above well to water injection. Due to delay in development, we wish to keep this well on active producing status until further notice.

RECEIVED

SEP 2 1 1964

D. C. C.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Ambassador Oil Corporation Fort Worth, Texas Address _____ Local - Box 260 Artesia