

APPROVED
MAR 22 1963

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. 023456(3)

RECEIVED

MAR 25 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	AA
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 21, 1963, 19

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 10

1/4 Sec. and Sec. No. 17 50 4
(Field) (Twp.) (Range) (Meridian)
Loco Hills Ady New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We acidized with 250 gallons 1-2 acid and 750 gallons super acid acid.
ran acid in stages of 3 bbls. shut down five minutes and pumped 3 bbls
more until all acid displaced. Let set 4 hrs. Well flowed over approximately
20 bbls (acid & water). Rigged up pump and snubbed approximately
40 bbls acid and water. Hooked up for injection.
Injection first 24 hours 401 bbls at 1450'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Newmont Oil Company

Address Rowley Building

Artesia, New Mexico

ORIGINAL SIGNED BY
H. J. LEDBETTER

By _____

Title Superintendent