

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N.M. D. C. C. COPY

SUBMIT IN TRIPLICATE
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-060529

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Beeson F

9. WELL NO.

#13

10. FIELD AND POOL, OR WILDCAT

Loco Hills

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31, T-17-S, R-30-E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

1. WELL TYPE
OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection

2. NAME OF OPERATOR

General American Oil Company of Texas

3. ADDRESS OF OPERATOR

P. O. Box 416, Loco Hills, New Mexico 88255

4. LOCATION OF WELL - Report location clearly and in accordance with any State requirements.
Specify 17 below

2310' FSL and 2232' FWL of Section 31,
Twp. 17-S, Rge. 30-E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3562' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

17. PURPOSE OF INTENTION TO

SUBSEQUENT REPORT OF:

17a. WATER SHUT-OFF

17b. DEEPEN OR ALTER CASING

17c. WATER SHUT-OFF

17d. REPAIRING WELL

17e. FRACTURE TREAT

17f. FILL IN COMPLETE

17g. FRACTURE TREATMENT

17h. ALTERING CASING

17i. SHOOTING OR ACIDIZING

17j. ABANDONMENT*

17k. SHOOTING OR ACIDIZING

17l. ABANDONMENT*

17m. OTHER WELL

17n. CHANGE PLANS

(Other) Shut-in Status

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DES. THE PROPOSER OF THE WORK TO BE DONE. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is to be plugged, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

We request that this well be held for possible testing after results are obtained from testing Beeson F # 11. If no favorable results obtained in Beeson F #11, this well should probably be plugged and abandoned.

Well was shut in November, 1963 for economical or mechanical reasons.

After feasibility studies are completed work should be commenced within the next two years.

RECEIVED

OCT 20 1974
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Roy Crow

TITLE District Superintendent

DATE Oct. 23, 1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY.

TITLE

WELL MUST

DATE

UNLESS FURTHER APPROVED
BE FOR TO PERMIT USE OR PLUGGED BY
OCT 1 - 1975

*See Instructions on Reverse Side

NOV

R. H. Baker

1947-1948

1947-1948
1947-1948
1947-1948
1947-1948