

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-04439
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-4108
7. Lease Name or Unit Agreement Name	
Tallmadge	
8. Well No.	1
9. Pool name or Wildcat	Loco Hills Queen G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter N : 990 Feet From The South Line and 1650 Feet From The West Line Section 32 Township 17S Range 30E NMPM Eddy County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Temporary Abandon <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-12-95 - Dug out cellar. Scraped off pad. Shut down.
7-13-95 - Built location. Break out rotten 7" casing above 8-5/8" wellhead. Installed new piece of 7" casing. Installed tubinghead. Nippled up BOP. Set and tested anchors and markers. Shut down.
7-14-95 - Filled in cellar. Moved in and rigged up pulling unit. TIH with bit, scraper and 2-7/8" J-55 tubing to 2700'. TOOH and lay down tubing, scraper and bit. TIH with CIBP and set at 2655'. Capped CIBP with 35' of cement. Tested 7" casing to 500 psi for 30 minutes, OK. Nippled down BOP and installed pressure gauge. NOTE: Notified Tim Gumm W/OCD - Artesia. TEMPORARY ABANDONED - 7-13-95.

JUL 19 1995

OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 7-17-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

TITLE _____ DATE _____

JUL 21 1995