

APPROVED**MAY 11 1962****RONNIE E. SHOOK**
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office **Las Cruces**Lease No. **060329**Unit **Basin 1****RECEIVED****MAY 15 1962****SUNDRY NOTICES AND REPORTS ON WELLS**

ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	1
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loce Hills, New Mexico May 2, 1962Well No. **17** is located **241.5** ft. from **100** line and **25** ft. from **150** line of sec. **31****Section 31** (Sec. and Sec. No.) **17-3** (Twp.) **10-2** (Range) **10-2** (Meridian)**Loce Hills** (Field) **547** (County or Subdivision) **New Mexico** (State or Territory)The elevation of the derrick floor above sea level is **3555** ft.**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On May 2, 1962 we ran 2742' of 5 1/2" OD 8rd 14# STAC new JS casing to 2744' and cemented with 141 sacks Incon 4/6# gel followed by 100 sacks neat Incon. We then pulled 10 3/4" casing loose and spotted 141 sacks Incon 4/6# gel around 10 3/4" shoe. We then pulled 10 3/4" casing. After standing 48 hours we drilled plug, bailed hole down and re-run bailer. As shut-off proved complete, drilling was resumed. Cementing was done by Benton Oil Well Cementing Company.

RECEIVED**MAY 15 1962****U.S. GEOLOGICAL SURVEY**
ARTESIA, N.M.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **General American Oil Company of Texas**Address **P. O. Box 426****Loce Hills, New Mexico**By **R. J. Heard**Title **District Superintendent**