

FREN OIL COMPANY

HILLS BUILDING
106-A TEXAS STREET
EL PASO, TEXAS

August 23, 1963

continued from page -1-

breakdown press.: 1400# - maximum press.: 1500# -
shut-in press.: 3000# - in 5 minutes 2800# -; injection rate: 15 B.P.M. -

sand frac zone : 3702' to 3712' in 5½" casing with: 14,406 gals. of lease oil;
9900# of 20/40 sand and 300# of glass beads -

breakdown press.: 1100# - maximum press.: 5300# -
shut-in press.: 3100# - in 5 minutes 2800# -; injection rate: 15 B.P.M. -

used 3" upset frac tubing .- Fracturing performed by Halliburton Company .

Results: It appears that the frac fluid and sand of both jobs channelled outside casing up-and-into the formerly producing gas zone at 3100'; as we are recovering load oil from and thru this zone to-gether with gas by snabbing and flowing .

There were 300 bbls. of load oil recovered up-to this date of writing.
We are trying to recover balance of some 550 bbls. of load oil at present .-

RECEIVED
AUG 26 1963
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO