NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS 00.5 (Submit to appropriate District Office as per Commission Rule 1106) Address Name of Company Beal. Trobaugh & Associates 122 Allen Building, Midland, Texas Lease Well No. Unit Letter Section Township Range Jones 31 -E 17-S Date Work Performed Pool County Robinson <u>Eddy</u> THIS IS A REPORT OF: (Check appropriate block) Casing Test and Cement Job Beginning Drilling Operations Remedial Work Plugging Detailed account of work done, nature and quantity of materials used, and results obtained. Spudded 8-31-59 Cmtd 9-5/8" 36# J-55 new Smls csg @ 740' w/300 sx and pressure tested to 1000 psi for 30 min. Cmtd 5-1/2" 15.5 J-55 ST&C @ 3678 w/150 sx and pressure tested to 3000 psi for 30 min. Position Witnessed by Company J. R. Stimmel Prod. Supt. Beal, Trobaugh & Associates FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA ΤD PBTD Completion Date Producing Interval DF Elev. 3678 <u>3538-3640</u> 9-26-59 3999 Oil String Diameter Oil String Depth Tubing Diameter Tubing Depth 211 3678 5-1/2" 3627 Perforated Interval(s) 3538-52.3560+62.3566-75.3596+3602.3632 Producing Formation(s) Open Hole Interval RESULTS OF WORKOVER Oil Production BPD Water Production GOR Gas Well Potential Date of Gas Production Test Cubic feet/Bbl MCFPD BPD MCFPD Test Before Workover After Workover I hereby certify that the information given above is true and complete to the best of my knowledge. OIL CONSERVATION COMMISSION

Approved by Title DAL MER BAS INSPECTO

10-2-

59

Date

Position

Stimm

Supt

Company

Name

Trobaugh & Associat

	STRICT OFFICE	
	and the control of th	3
	The state of the s	
	1 031-02-1	<u>-</u>
**		
v. 3. 5.	-	
Samuel Samuel	<i>†</i>	
	\	
BURGAU OF MINES		/

· ·