

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106) O. O. O.

RECEIVED

FORM C-103
(Rev 3-55)

DEC 28 1959

Name of Company Beal, Trebaugh & Associates		Address 122 Allen Building, Midland, Texas				
Lease Featherstone	Well No. 4	Unit Letter D	Section 2	Township 17-S	Range 31-E	
Date Work Performed	Pool Robinson			County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spudded 11-24-59**Cmt 9-5/8" csg @ 388' w/175 sx; 36# J-SmIs new
WOC 24 hrs; tested to 3000# for 30 minutes o.k.**

Witnessed by	Position Pred. Supt.	Company Beal, Trebaugh & Associates
--------------	--------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s) Grayburg		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

Name

Position

Company

Title

Date

OIL AND GAS INSPECTOR

Production Supt.**Beal, Trebaugh & Associates**

DEC 28 1959

RECEIVED	NOV 11 1918
U. S. DEPT. OF THE INTERIOR	
BUREAU OF LANDS	
WASHINGTON, D. C.	
TO THE SECRETARY	
FROM THE LAND OFFICE	
SUBJECT: [illegible]	
RE: [illegible]	
DATE: [illegible]	
FILE	
BUREAU OF MINES	