



*copy sent
8-4-54*

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Office Las Cruces
Lease No. 029426(a)
Unit West A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Tulsa, Oklahoma July 23, 19 54

Well No. 4 is located 1980 ft. from N line and 1980 ft. from E line of sec. 4

NE 1/4 Sec. 4
(1/4 Sec. and Sec. No.)

17 South 31 East
(Twp.) (Range)

(Meridian)

Grayburg-Jackson
(Field)

Eddy County
(County or Subdivision)

New Mexico
(State or Territory)

Sy. Lake

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SINCLAIR OIL & GAS COMPANY NO. 4 - H. E. WEST "A"

8-5/8" csg	22.74#	NEW	500'	100 sacks cement
7" csg	17#	NEW	2200'	200 sacks cement
7" csg	20#	NEW	1500'	

Contract to be made for a total depth of 3700' to test the Grayburg-San Andres Dolomite 3150' to total depth.

To be drilled with cable tools.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SINCLAIR OIL & GAS COMPANY

Address BOX 521, TULSA, OKLAHOMA

By _____

Title Asst. General Supt., Prod. Dept.