



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau 42-R258.3.  
Approval expires 12-31-55.

Land Office **Las Cruces**  
Lease No. **029426 (A)**  
Unit **H. E. West "A"**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 11, 1954

Well No. 5 is located 1980 ft. from S line and 1980 ft. from E line of sec. 4  
SE/4 Sec. 4 173 31E  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Grayburg-Jackson (E. 7) Eddy New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SINCLAIR OIL & GAS COMPANY - Well No. 5

8 5/8" csg	22.74#	NEW	500'	100 sacks cement
7" csg	17 - 20#	NEW	3650'	200 sacks cement

Contract to be made for a total depth of 3650' to test the Grayburg-San Andres dolomite 3150' to total depth.

To be drilled with cable tools.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SINCLAIR OIL & GAS COMPANY

Address 901 Fair Building, Fort Worth, Texas

By J. G. Reeves

Title Division Superintendent  
Production Department