



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 88435 (b)  
Unit 4. L. Well 73

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. Keel "B" is located 1960 ft. from 200 line and 560 ft. from 500 line of sec. 9  
(N) (S) (E) (W)  
200 (1/4 Sec. and Sec. No.) 200 (Twp.) 200 (Range) 200 (Meridian)  
200 (Field) 200 (County or Subdivision) 200 (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2000-2000 ft. - 2000 ft. - 2000 ft. - 2000 ft. - 2000 ft.

8 1/2" 200 2000 200 200

7" 200 2000 200 200

Propose to drill to 2000' to test the Graptolite Sand 2000-2000', San  
Andrew Wells 2000-2000' TH.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SUNCLAY OIL & GAS COMPANY

Address P. O. Box 1470

Midland, Texas

By

A. F. DeFurough  
Title Division Supt., Production Dept.