

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TI  
(Other Instruct.  
verse side)

ICATE\*  
on re-

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
Las Cruces 029435(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
J. L. Keel "A"

9. WELL NO.  
8

10. FIELD AND POOL, OR WILDCAT  
Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

7-T17S-R31E

1. OIL ☒ GAS ☐ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR  
SINCLAIR OIL & GAS COMPANY

3. ADDRESS OF OPERATOR  
P. O. Box 1920, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' fr the South and East lines of Section 7-T17S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3705' DF

12. COUNTY OR PARISH  
Eddy

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☒  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well presently completed in Grayburg Jackson 2761-3482'. TD 3528', PBTD 3482'.  
Presently producing 9 BOPD and 15 BWP.

PROPOSE TO: Plug back w/frac sand to approx. 3260'. Frac OH interval 2761-3260' (Metex, Sq. Lake, Premier, Vac. & Lov.) w/ approx. 15,000 gals. gel water and 15,000# sand in 3 stages. Clean out to PBTD 3482' and return to production.

RECEIVED

AUG 17 1967

O. C. C.

ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

8-15-67

RECEIVED  
AUG 16 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

APPROVED  
AUG 16 1967  
R. L. ULLMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

Orig&cc: USGS, Artesia, N.M.  
cc: Regional Office  
cc: file