

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI  
(Other instructi  
verse side)CATE\*  
on reForm approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC 029426 (b)	
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.) See also space 17 below.) At surface  660' FNL & 660' FWL (Unit letter D)		8. FARM OR LEASE NAME H. E. West "B"	
14. PERMIT NO.		9. WELL NO. 8	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3882' GR		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7 Rivers	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 9-17S-31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Attempted recompletion to Seven Rivers zone in the following manner:

1. Ran cmt bond log 2500-600'. Found TOC behind 7" OD csg @ 1575' from surface.
2. Ran GR-N log 2893-1500'.
3. Ran 2-7/8" tbg in hole OE & spotted 7 bbls 15% HCL-LSTNE acid 2161-2088'. POH w/tbg.
4. Perf'd 1 JS ea @ 2100.5', 13, 24, 36, 2214, 26, 44 & 2261' = 8 holes. New PBD 2446'.
5. WIH w/pkr on 2-7/8" tbg, set pkr @ 2032', trtd perfs 2100½-2261' w/2000 gals 15% HCL-LSTNE acid w/10 gal/1000 L-42 added. Flushed w/31 bbls 4% KCl wtr. MP 3100#, Min 1550#, ISIP 700#. Dropped 12 ball sealers w/good action. 15 min SIP 600#, rel press. Swbd perfs 2100½-2261' 24 hrs, rec 79 BLW & 83 BNW w/no oil & slight show of gas. IFL surf, FFL 1700'. Rel pkr & POH. Recompletion attempt to Seven Rivers unsuccessful. Preparing to P&A well, no other zones of interest exist. Recompletion attempt completed 6/4/76.

RECEIVED

JUN 15 1976

U. S. GEOLOGICAL SURVEY  
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 6/14/76

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side