5-USGS-ARTESIA 1-R. J_ STARRAK-TULSA 1-FIL NMOCC COPY

1-FILE

1-A.B. CARY-MIDLAND

5. LEASE

Form Approved. Budget Bureau No. 42-R1424

Form 9-331 Dec. 1973

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas other	Skelly Unit 9. WELL NO. 31
2. NAME OF OPERATOR Getty Oil Company	10. FIELD OR WILDCAT NAME Grayburg Jackson
 3. ADDRESS OF OPERATOR P. O. BOX 730, HODDS, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	20 2.1
AT SURFACE: Unit Letter O 660' FSL & 1980' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Fady New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Casing Connections	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin	Chechough dimed Fire passanters
Riser on 10 3/4" OD and 8 1/4" OD casing b	rought to surface.
Inspected by B. W. Weaver (NMOCC) on Inspected by Mike Williams (NMOCC) on	MAY 7 1979
Inspected by Fire Williams (Masses, on	APR 2 6 1979 . ARTESIA, OFFICE
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. Thereby certify that the foregoing is true and correct SIGNED Area Su	APR 2 7 1979
D. R. Crockett (This space for Federal or State of CTING DISTRICT EN	e office use) GINEER DATE MAY 1 1979