

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN 1
(Other instruct
verse side)

ICATE*
ON TO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0467934

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Tr. MB
Grayburg-Jackson WFL

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

11. SEC., T., R., M., OR BLM. AND
SUBVY OR AREA

Sec. 27, 17-S, 30-E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for each proposal.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit L, 1815' FSL & 1295' FWL

SEP 22 1992

14. PERMIT NO.

API No. 30-015-20256

15. ELEVATIONS (Show whether SP, RT, OR, etc.)

3624' GL

O. C. D.
OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Acidize, press tst & swab

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-21-92: MI & RU. Pump 500 gal Pentol 200 (15%) acid.

4-22-92: Swab.

4-23-92: Release pkr. GIH with RBP & pkr. Set RBP at 3080'. Test casing to 500#.

4-27-92: RU & run rod & pump string. Ran 2-1/2 X 2 X 12. Insert pump.

5-1-92: Put well pumping to test tank.

7-1-92: Test 24 hrs Bbls of water - 2; Gravity of oil - 37; Bbls of oil - 3; Gas-MCF - .33; GOR - 127; complete drop from report.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders
L. M. Sanders

TITLE Supervisor Regulatory Affairs DATE 8/3/92

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side