

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED
NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

RECEIVED

SEP 23 1982

O. C. D.

d/sf

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	FED <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NM 074935	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT ZONE. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

ARTESIA, OFFICE

RECEIVED

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Anadarko Production Company ✓	8. Farm or Lease Name Loco Hills Fed. A
3. Address of Operator P. O. Drawer 130, Artesia, New Mexico 88210	9. Well No. 3
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>17S</u> RANGE <u>30E</u> N.M.P.M.	10. Field and Pool, or Wildcat Grayburg-Jackson
15. Elevation (Show whether DF, RT, GR, etc.) 3701' GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Repair Water Flow</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- On 8-18-82 this well developed a braidenhead waterflow. Water flowed at the rate of 1.5 BPM out of the 8-5/8" surface casing.
- Mr. Les Clements was called on 8-18-82 & notified of waterflow.
- General American performed 3 cement squeeze jobs on their offset well - Parke #2 about the first of September 1982.
- On 9-5-82 our Federal A #3 quit flowing. Since that time we have left the braiden-head valve open (to monitor) and the waterflow is dead. It appears that General American solved the problem.

RECEIVED
SEP 20 1982

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry E. Mueller</u>	TITLE <u>Area Supervisor</u>	DATE <u>Sept. 8, 1982</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

ACCEPTED FOR RECORD

SEP 21 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO