ormerly 9	=331) DE	PART NT OF BUREAU OF LAN	THE INTERI		LC#28793-C	AND SERIAL NO.	
(1)0		NOTICES AN		ON WELLS ack to a different reservoir. oppossis.)	6. IF INDIAN, ALLOTTE		
OIL X	GAS WELL	OTREE		RECEIVED	7. UNIT AGREEMENT NAME		
2 NAME OF Philli 3. ADDRESS	ps Petrole	ım Company		FEB - 4 1992 O. C. D.			
4001 Penbrook Street, Odessa, Texas 79762 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below) At surface					10. FIBLD AND POOL, OR WILDCAT		
Unit H	I, 1980' FNI	Gb/Jackson SR-Q-GB-SA 11. SBC, T., B., M., OR BLK. AND SURVEY OR AREA					
14. PERMIT N	10.	15. ELEVATI	ons (Show whether DF,	RT, GR, etc.)	Sec. 18, 17-	-S, 30-E	
API No	30-015-20	0623	3648' GL		Eddy	NM	
16.	Ch	ieck Appropriate E	Box To Indicate N	ature of Notice, Report, or	Other Data		
	NOTICE OF INTENTION TO:					UENT REPORT OF:	
FRACTUR BHOOT O REPAIR V (Other) 17. DESCRIBE Propose							
1-20-92	Got to 235 Shaw to see dump Baile culate and 300#. Dornhead leaking GIH with panother 4-	age ring to 23 to 0, COOH. Callet CIBP at 235 er and dump 1 d load hole with Early with Eing. COOH with eacker, casing -1/2" leak about 1	B50, COOH. Galled BLM and Go. GIH and sack of cements in 36 bbls in BLM witnessed the tubing. The control of t	interval and TA wel IH with scraper on got verbel permissi set 4-1/2" CIBP at nt on CIBP, appx. 8 nhibited fluid. Pr integrity test. P /2" casing between n 8-5/8" packing he ole in 8-5/8" below	2-3/8" workstring on from Shannon 2347." GIH with of cement. Caresure casing to acking on 8-5/8" 505' and 513'.	ng ir- o ' Had in	
workstring. 1-22-92 Dug out 8-5/8" casing 12'. Found no hole, Pumped into 8-5/8" casing, water came up in celler. Waiting on proposal, review for P.&A. Temp. Drop From Report.							
SIGNED _	that the for	egoing is true and cor fle flat tate office use)		ervisor Reg/Prorati	on (915) 368	92 -1488	
APPROVE	D BY ONS OF APPROVA	L, IF ANY:	TITLE		DATE	N	
					3 199	び 50S	

*See Instructions on Reverse Side