

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0555569

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒

DRILLING

RECEIVED

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY

NOV 7 1974

3. ADDRESS OF OPERATOR

BOX 367, ANDREWS, TEXAS 79714

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surfaceO. G. E.
ARTESIA, OFFICE

1980' FNL x 2180' FEL Sec. 31 (Unit 4, SW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3640' GL

7. UNIT AGREEMENT NAME

EMPIRE SOUTH DEEP UNIT

8. FARM OR LEASE NAME

Lower Empire Deep Unit

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

So. Empire-Morrow-GAS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

31-17-29 NMDM

12. COUNTY OR PARISH 13. STATE

EDDY

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 8-28-74, 8 5/8" OD 24-32" H-40 & K-55 Casing was
 set @ 2825' w/ 1290 Sx (1090 Sx Trumity Lk wt x 7" St/Sx
 x 0.2% CFR-2 x 1/4" Flocele/Sx + 200 Sx Incon) After
 WOC 18hr. Tstg @ 950 psi for 30 min. Test O.K.
 Reduced hole to 7 7/8" @ 2835' & resumed drilling.

RECEIVED

NOV - 5 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE ADMINISTRATIVE ASSISTANT

DATE NOV 1 1974

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

 0-4- USGS-DET
 1-DIV
 1-SUP
 1-REV
 1-CHG
 1-CON
 18-OTHERS

APPROVED

NOV 6 - 1974

H. L. BEEKMAN
DISTRICT ENGINEER

*See Instructions on Reverse Side