

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-21004

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use APPLICATION FOR PERMIT for such proposals.)

|                                                                                                                                                                                                                                                     |  |                                                                               |  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                                                                    |  | 7. UNIT AGREEMENT NAME<br>Square Lake 12 Unit                                 |  |
| 2. NAME OF OPERATOR<br>Kewanee Oil Company                                                                                                                                                                                                          |  | 8. FARM OR LEASE NAME<br>Tract 2                                              |  |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 3786, Odessa, Texas 79760                                                                                                                                                                                       |  | 9. WELL NO.<br>2                                                              |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>Unit N, 990' from West line and 990' from South line, Section 12, T-17-S, R-29-E, Eddy County, New Mexico |  | 10. FIELD AND POOL, OR WILDCAT<br>Square Lake G-SA                            |  |
| 11. SEC., T., R., or BLK. AND SURVEY OR AREA<br>12, T-17-S, R-29-E                                                                                                                                                                                  |  | 12. COUNTY OR PARISH<br>Eddy                                                  |  |
| 13. STATE<br>New Mexico                                                                                                                                                                                                                             |  | 14. PERMIT NO.                                                                |  |
| 15. ELEVATION (Show whether DE, RL, or etc.)<br>3640' G.L.                                                                                                                                                                                          |  | 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data |  |

|                                                                                                                                                                                |                 |                                                                                                     |                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------------------------------------------------------------------------|-----------------|
| NOTICE OF INTENTION TO:                                                                                                                                                        |                 | SUBSEQUENT REPORT OF:                                                                               |                 |
| TEST WATER SHUT-OFF                                                                                                                                                            | PLUG OR ABANDON | WATER SHUT-OFF <input checked="" type="checkbox"/>                                                  | REPAIRING WELL  |
| FRACURE TREAT                                                                                                                                                                  | RE-ENTRY        | FRACURE TREATMENT                                                                                   | ALTERING CASING |
| SHOOT OR ACIDIZE                                                                                                                                                               | ABANDON*        | SHOOT OR ACIDIZING                                                                                  | ABANDONMENT*    |
| REPAIR WELL                                                                                                                                                                    | CHANGE DEPTH    |                                                                                                     |                 |
| (Other)                                                                                                                                                                        |                 | Note: Report results of multiple completion on Well Completion or Recumpletion Report and Log form. |                 |
| 17. DESCRIBE PROPOSED WORK. If well is directionally drilled, show subsurface location and measured and true vertical depths for all markers and zones pertinent to this work. |                 |                                                                                                     |                 |

8-9-74 - Spudded well with rotary rig.

8-10-74 - Drilled 12-1/4" hole to 510'. Set 8-5/8" casing at 505'. Cemented with 100 sacks HOWCO Lite cement and 100 sacks Class C cement with 2% CaCl. Cement did not circulate. Filled annulus with 14 yards Redimix. While drilling had lost circulation at 80', dry drilled to 510'. Tested pipe to 1000 psi for 30 minutes after 12 hours with no loss in pressure.

RECEIVED

AUG 12 1974

U.S. GEOLOGICAL SURVEY  
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

*W. B. Stone*

TITLE

Production Supervisor

DATE

8-12-74

(This space for the operator's office use.)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side