

N. M. O. C. C. COPY
UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE
(Other instructions on
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-062407

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **DRILLING**

2. NAME OF OPERATOR **AMOCO PRODUCTION COMPANY**

3. ADDRESS OF OPERATOR **BOX 367, ANDREWS, TEXAS 79714**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FSL v 1241' FWL Sec 33 (Unit 1, NW/4 SW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3547' GL

7. UNIT AGREEMENT NAME
EMPIRE SOUTH DEEP UNIT

8. FARM OR LEASE NAME
EMPIRE SOUTH DEEP UNIT

9. WELL NO.
8

10. FIELD AND POOL, OR WILDCAT
GRAYBURG-MORROW-GAS

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
33-17-29 NM PM

12. COUNTY OR PARISH
EDDY

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Sharp Drilling Co spudded 17 1/2" hole 7:30 PM-2-22-76
On 2/24/76 13 3/8" OD 54.50' K-55 ST&C was set @
394' w/ 400 24 class @ + 2% CACL + 1/4" / 5x celloflakes.
Circ. 63 5x. woc 18 hours tested casing w/
1000 psi for 30 min. Best. OK.

Reduced hole to 12 1/4" @ 394 and resumed
drilling.

RECEIVED

MAR - 1 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ray A. Grooms

TITLE

ADMINISTRATIVE ASSISTANT

DATE

FEB 24 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

0+4- USGS - Act

1-DIV

1-SUSP

1-RRV

20-PARTNERS

TITLE

DATE

MAR - 2 1976
R. L. BEEKMAN

ACTING DISTRICT ENGINEER See Instructions on Reverse Side