

Lakes, Streams & Ponds - none.

Gullies - this location lies directly in the bottom of a gully or sink hole. All of the surrounding countryside is at a higher elevation. The drainage area leading to this depression is relatively small and the soil consists of only loose sand, therefore, surface water does not collect at this point.

Dwellings - none.

Other Facilities - none.

Archaeological Sites - none.

Historical Sites - none.

Cultural Sites - none

12. Operator's Representative - Jerry E. Buckles  
Anadarko Production Company  
Area Supervisor  
Office Phone - 505-677-2411  
Home Phone - 505-396-4036

13. Certification - I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Sweatt Construction Company and its contractors and sub-contractors in conformity with this plan and the terms and conditions under which it is approved.

June 23, 1976  
Date

 , Area Supervisor  
Name and Title

