

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE.
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029419-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Skelly Unit

9. WELL NO.

118

10. FIELD AND POOL, OR WILDCAT

Fren-7 Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

22-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Getty Oil Company ✓

3. ADDRESS OF OPERATOR

Box 730, Hobbs, N. Mex. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1880' FSL and 660' FEL, Sec. 22

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3841 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

LaRue Drilling Company spudded 10:30 A.M. 11-15-77. Drilled 11" hole to 630'. Set 8-5/8" 24# 8R K-55 R3 ST&C Casing at 630'. Dowell cemented with 125 sacks 50/50 poz., 4% gel, 1/4# Cello Flakes per sack and 150 sacks Class C w/2% Cacl₂. Cement circulated. WOC 16 hours. Tested 8-5/8" casing with 1000# for 30 minutes, no drop in pressure.

RECEIVED
JAN 10 1978
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Supt.

DATE 1-9-78

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE

JAN 13 1978

CONDITIONS OF APPROVAL, IF ANY: