

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-029420-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
GETTY OIL COMPANY ✓

3. ADDRESS OF OPERATOR
P. O. BOX 730, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
UNIT LETTER K, 2130' FSL, AND 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3867' GL

7. UNIT AGREEMENT NAME
Skelly Unit

8. FARM OR LEASE NAME

9. WELL NO.
151

10. FIELD AND POOL, OR WILDCAT
Fren 7-Rivers

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA
SEC. 15, T-17-S, R-31-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

La Rue Drilling Co. spudded 11" hole at 3:00 p.m. on 6-8-78. Drilled 11" hole to 583'. Set 8 5/8" 24# casing at 582', and cemented with 150 sxs. Lite Cement, 4% Gel, 10# Salt, with 1/4# Flo-Cele/sk. and 125 sxs. Class "C" Cement with 2% CaCl. 28 sxs. cement circulated. Waited on cement 12 hrs. Tested casing with 1000# for 30 minutes with no drop in pressure.

RECEIVED

JUL 27 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett

TITLE AREA SUPERINTENDENT

DATE 7-24-78

(This space for Federal or State office use)

APPROVED BY Lee J. Lora

TITLE ACTING DISTRICT ENGINEER

DATE JUL 28 1978

CONDITIONS OF APPROVAL, IF ANY:

