

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED	5. LEASE DESIGNATION AND SERIAL NO. LC-029418-B
2. NAME OF OPERATOR Getty Oil Company	JUL 27 1978	6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----
3. ADDRESS OF OPERATOR P.O. Box 730 Hobbs, New Mexico 88240	U.S.G. ARTESIA, OFFICE	7. UNIT AGREEMENT NAME Skelly Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter O, 510' FSL & 1980' FEL		8. FARM OR LEASE NAME -----
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3861'	9. WELL NO. 139
		10. FIELD AND POOL, OR WILDCAT X Fren 7-Rivers
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T-17-S, R-31-E
		12. COUNTY OR PARISH Eddy
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Drilled 7 7/8" hole to 2679' and set 5 1/2" 15.5# J-55 casing at 2679'. on 6 - 7, 1978. B.J. cemented with 600 sxs. Lo-Density cement, 10# salt, 1/4# Cello Flakes/sx. 200 sxs. Class "C" cement w/2% CaCL. Total cement 800 sxs. Cement circulated 91 sxs. Tested casing with 1500# for 30 minutes with no drop in pressure.

RECEIVED
JUL 21 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) D. R. CROCKETT	TITLE Area Superintendent	DATE 7-20-78
(This space for Federal or State office use)		
APPROVED BY <i>[Signature]</i>	TITLE ACTING DISTRICT ENGINEER	DATE JUL 26 1978
CONDITIONS OF APPROVAL, IF ANY:		